

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	Dennis Ware Controller				
OGM Steve Demczak Environmental Scientist III					

Inspection Report

Permit Number:	C0070038		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, June 11, 2008		
Start Date/Time:	6/11/2008 10:00:00 AM		
End Date/Time:	6/11/2008 12:00:00 PM		
Last Inspection:	Tuesday, May 20, 2008		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 70's

InspectionID Report Number: 1680

Types of Operations

Accepted by: jhelfric

7/7/2008

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP

Site: WILLOW CREEK MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

14,662.49	Total Permitted		
71.44	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

✓ Federal ✓ Underground

☐ State ☐ Surface

☐ County ✓ Loadout

✓ Fee ☐ Processing

✓ Other ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Steve Demozak Environmental Scientist III

Date

Tuesday, June 17, 2008

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Wednesday, June 11, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓			
2.	Signs and Markers				
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		V	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	V		✓	
13.	Revegetation	✓		✓	
14.	Subsidence Control		✓		
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070038
Inspection Type: PARTIAL

Inspection Date: Wednesday, June 11, 2008

Page 3 of 3

3. Topsoil

All topsoil was used to reclaim the loadout area.

4.a Hydrologic Balance: Diversions

The diversion was spot-checked and would function during a storm event.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

No impoundments are in the permit area.

4.c Hydrologic Balance: Other Sediment Control Measures

The permittee used pocking to control sediment. No sediment was leaving the site during the inspection.

4.d Hydrologic Balance: Water Monitoring

The permittee has submitted fourth quarter water information to the Division.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile has been reclaimed.

8. Noncoal Waste

The site is clear of non-coal waste material.

10. Slides and Other Damage

No slides were noticed during the inspection.

12. Backfilling And Grading

The site is completely backfilled and graded.

13. Revegetation

The areas has been seeded and vegetation is established throughout the reclaimed site.